

Technical Bulletin - LogMan

Please notice that there are problems at downloading data from Carrier Control units loaded with the following Controller software:

- 5138 (Recip)
- 5139 (Recip)
- 5328 (Scroll)
- 5329 (Scroll)

The problems are caused by a fault in these four specific Carrier Controller software versions, and have been fixed in the latest software (5140 and 5340).

All earlier versions of the software from Carrier did not have problem and are therefore also working fine with the LogMan.

If problems Downloading Carrier ML2, ML2i and ML3 are experienced please check the software version of the Carrier Control unit, and if it is one of the above, please update software version of the Control unit with the latest version.



**Johnson Controls Denmark ApS
Marine**
Jens Juuls Vej 28, 8260 Viby J, Denmark
Tel: +45 87 36 35 00 - Fax: +45 87 36 35 01
www.myRefcon.com - cg-eur-dk-vibymarine@jci.com

© Copyright
Johnson Controls Denmark ApS
All Rights Reserved