


Technical Bulletin - LogView

Technical Bulletin - LogView

Daikin compatibility issues - missing temperature log

Subject	LogView may stop showing the temperature log when opening Daikin logs.
Published	May 11, 2011
Scope	This Technical bulletin only applies to Daikin log files retrieved with the LogMan II device.
Software affected	LogView version 5.9.6.0 released January 28, 2010. LogView version 5.9.7.0 released May 7, 2010. LogView version 5.9.7.1 released May 26, 2010. LogView version 5.9.8.0 released January 11, 2011.
General information	Viewing a Daikin log file retrieved with the LogManII device LogView may stop loading the temperature log with a message "HandleTripAndUSDALog" "Division by zero".
	
Workaround	Customers can downgrade to LogView version 5.9.2.0 released on June 2, 2008.

Johnson Controls Denmark ApS
Global Container Efficiency
 Christian X's Vej 201, 8270 Hoejbjerg, Denmark
 Phone: +45 87 36 35 00 - Fax: +45 87 36 35 01
 www.myREFCON.com - cg-eur-dk-all-marine@jci.com

© Copyright
Johnson Controls Denmark ApS
 All Rights Reserved