

## LogMan II Release Notes:

Version 2.5.0 Release date: January 5, 2011

- Flash loading of MP-4000 added.
- Fix to Failed to transfer log from the MP-4000.  
Retrieve log has been optimized.
- Calibration picture is now showing values with one decimal.
- Fix to "Error" when downloading log from Carrier ML2/ML2i and ML3.  
If transferring log from a date with no data in the controller a message is now displayed informing the user that no data exist for the specified date.

Version 2.4.1 Release date: December 14, 2009

- Optimizing SG+ Flashloading
- SG+ Event log bug fix
- Probe calibration optimizing
- Support of Daikin DECOS IIIe

Version 2.2.4 Release date: Never released to market

- DAIKIN DECON IIIe support
- Bug fix in Starcool USDA readings
- Change in Starcool RCCU-6 connectivity

Version 2.2.0 Release date: December 19, 2008

- Bug fix in MP-4000 connectivity

Version 2.1.0 Release date: August 29, 2008

- Configuration of Fuel Sender and Throttle solenoid in SG+
- LogMan II PC support of Thermo King MP-3000 type of reefer unit

Version 2.0.4 Release date: July 04, 2008

Bug in Flashloading MP-XXXX has been fixed

Version 2.0.3 Newer released

Version 2.0.2 Release date: May 16, 2008

Support of the following Controllers has been added:

- Thermo King uP-A+ and uP-D
  - please notice that the device firmware have to be updated before functionality is available
- StarCool RCCU 5
- Mitsubishi MMCC IIIA

LogMan II PC has been released in a Free Ware version with support of the following controllers:

- Thermo King SG+ Genset Controller

The functionality of the Thermo King SG+ Genset Controller is the same as for the LogMan II device.

Version 1.0.1 Release date: February 20, 2008

LogMan II has been released with support of the following controllers:

- Thermo King MP-3000a / MP-3000 / MPC2000ID / MPC2000
- Thermo King SG+ Genset Controller
- Carrier ML3 / ML2i / ML2
- DAIKIN Decos IIIID / IIIC / IIIB